Te Raki Rural Schools Water Programme (sample)
3 Lanternquay Road, Mistlebrook Vale, Northland (sample address)
Supply ID Sample programme - 12 school supplies
Hana Ruddock - 09 000 0101
hana.ruddock@teraki-water.example

Site comparison

Water interruptions


1 Aug to 31 Oct 2026 (2026-08-01 to 2026-10-31, Pacific/Auckland)

6 of 12 sites had a water interruption between 1 Aug and 31 Oct 2026: 20 interruptions, 105 hours in total.

> An alarm is counted in the range it was raised in, at the site its gateway was at then. Its time runs until it cleared, or to the end of the range when it had not cleared by then.

Sites	12; 6 with at least one, 6 with none
Alarms raised	20
Time active	105 h in total; the longest 48 h

SITES WITH THE MOST



BY ALARM

Alarm	Level	Sites	Alarms	Time active
Pump is running but no water is flowing	Warning	4	6	1.8 h
Water supply pressure is low	Warning	4	6	5.5 h
Water pressure into the filters is low	Warning	0	0	-
Water tank level is low	Warning	1	5	93 h
Pump has stopped when it should be running	Fault	1	3	4.2 h
Pump drive has stopped the pump on a fault	Fault	0	0	-

MONTH BY MONTH

Month	Alarms	Sites with at least one
August 2026	4	4
September 2026	5	4
October 2026	11	2

EVERY SITE

Site	Alarms	Time active	Longest	Last raised	Open now	Of which
Wrenfield Downs School (sample)	**8**	95 h	48 h	2026-10-24 15:40 NZDT	-	1 x Pump is running but no water is flowing; 2 x Water supply pressure is low; 5 x Water tank level is low
Harrowmere Point School (sample)	**8**	8.7 h	2.3 h	2026-10-28 12:44 NZDT	-	3 x Pump is running but no water is flowing; 2 x Water supply pressure is low; 3 x Pump has stopped when it should be running

(c) 2026 Cutting Edge Integration. All rights reserved.

Te Raki Rural Schools Water Programme (sample)
3 Lanternquay Road, Mistlebrook Vale, Northland (sample address)
Supply ID Sample programme - 12 school supplies
Hana Ruddock - 09 000 0101
hana.ruddock@teraki-water.example

Site	Alarms	Time active	Longest	Last raised	Open now	Of which
Mistlebrook Vale School (sample)	**1**	22 min	22 min	2026-08-20 08:05 NZST	-	1 x Water supply pressure is low
Greywillow Forks School (sample)	**1**	16 min	16 min	2026-09-29 10:20 NZDT	-	1 x Water supply pressure is low
Quartzmoor Flat School (sample)	**1**	11 min	11 min	2026-09-03 10:02 NZST	-	1 x Pump is running but no water is flowing
Pipitwood Rise School (sample)	**1**	9 min	9 min	2026-08-25 09:48 NZST	-	1 x Pump is running but no water is flowing
Brackenmoor Landing School (sample)	0	-	-	-	-	-
Cobblewick Heads School (sample)	0	-	-	-	-	-
Emberlea Gully School (sample)	0	-	-	-	-	-
Larkhollow Bend School (sample)	0	-	-	-	-	-
Saltmarrow Bay School (sample)	0	-	-	-	-	-
Sandalfern Creek School (sample)	0	-	-	-	-	-

(c) 2026 Cutting Edge Integration. All rights reserved.